# **RECEIVED**DHSS Breath Alcohol Program By Carol Day at 3:41 pm, Nov 10, 2009



### MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY DATAMASTER MAINTENANCE REPORT

Morgan Co. SO, Versailles

Complete this is repaired. Sen	report in dup d copy to Dep	licate at the	e time of the Health; reta	ne regular iin origina	monthly p	reventive m ent file,	aintenance	check, a	nd whenever l	nstrument
DATAMASTER SN 204158						DATEO	DATE OF INSPECTION			
LOCATION OF INSTRUMENT (STREET AND CITY)						TIME OF	11/10/2009 INSPECTION			
2920 North Shamrock Road, Jefferson City  CHECKLIST: Place a check (<) to the left of each item if found to be satisfactory or if operating						13:01				
in observed valu	lace a check : ies where dete	(✓) to the l ermined.) L	eft of each Inchecked II	item if fou tems must	ind to be sa be correcte	tisfactory o d before us	r if operating	g within	established Ilm	ilts. (Write
☑ DIAGNOST										
✓ COMPI	JTER				<b>⊘</b> DET	ЕСТОЯ				
✓ PROGRAM			☑ FILTERS							
☑ HEATERS SAMPLE CHAMBER +50°C			☑ QUARTZ STANDARD							
<b>√</b> FLOW (	✓ FLOW DETECTOR			☑ CALI	☑ CALIBRATION					
✓ PUMP I	HGH SPEED				<b>⊘</b> PRIN	TER	·			
☑ INDICATOR	LIGHTS	- '			······································	<del></del>			·	
TIME AND I	DATE		·· <del>·</del> ········		····-					
<b>☑</b> SIMULATO	R TEMPERAT	URE (34 °C	± 0.2°C)	+33.98°C						
spread of .0 RECIRCULA ☐ 0.100% S ☑ 0.040% S	05 or less. Ci NTION PUMP) TANDARD - N TANDARD - N STANDARD	NUST REA	ox correspo D BETWEE! D BETWEE!	nding to N 0.095% a N 0.038% a	the standard and 0.105%   and 0.042%	solution to INCLUSIVE	eing used.	PRINTO	value and mus PUT ATTACHE	D) (USE
TEST 1 FF	.039		TEST 2		.040		TEST 3	<b>9</b> 4"	.040	
PERFORM P	I.F.I. TEST (PI	RINTOUT	ATTACHED	)				····		
NUMBER OF FOLLOWS:	REFUSALS,	SINCE LAS	T ROTALUM	NANCE RE	PORT, AND	NUMBER	OF BREATH	I TESTS	IN EACH RAN	IGE AS
REFUSALS 0	(004)	0	(.0509)	0	(.1014)	0	(.1519)	0	(Over .19)	0
List any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactorily and within established limits (use other side if necessary)  Jumpered defective trace on power supply PC board supplying +5VDC analog supply for proper continuity. Confirmed proper voltage settings on power supply PC board, as well as voltages to sample chamber control PC board (flow rate voltage adjustments made).										
Cult I abandad	1-1-1100040									
Guth Laboratorie NSPECTING OF		expiring 01,	/06/2010	- ·						
IGNATURE COLU	Josepho la		eruly		PRINT NAME Dewa	yne D. Carv	er			
YPE II PERMIT NUMBER 9202	EXPIRATION DATE	09/07/2			TELEPHONE (573)	NUMBER 751-4722				

### CERTIFICATE OF ANALYSIS

MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc. LOT NUMBER: 09001

EXPIRATION DATE: April 22, 2011 at 11:59 p.m.

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number <u>09001</u> of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed by an independent laboratory utilizing a gas chromatograph and found to contain <u>.1214</u> gms/dl +/-.003 gms/dl wt/vol ethanol (95% Confidence).

The alcohol and distilled water used in the solution were found to be free of any interfering substance.

This solution will produce a vapor alcohol value of <u>.100</u> +/-3% gms/210L Breath when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator (95% Confidence).

The date of manufacture for this lot number is April 23, 2009.

The expiration date for this lot number is April 22, 2011 at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.

Cecil B. Garner, President RepCo Marking, Inc.

Form RM 02

# FACE THIS SIDE DOWN - THIS EDGE IN FIRST

**BAC DataMaster** Evidence Ticket

BAC DATAMASTER SERIAL NUMBER 204158 MISSOURI STATE HIGHWAY PATROL

QKA? SKA7 GKAY --- DIAGNOSTIC CHECK 11/18/89 13:61 PROGRAM (04-07-2009): HEHTERS SAMPLE CHAMBER: FLOW DETECTOR: HIGH SPEED DETECTOR: FILTERS:

1. ##282.(0)\*+, -, / Ø1/03456/891.; < | >/@CBCDCDEFG HIJKLMNOPQRSTUVWXYZ[\]^.'abcdefghijklmno FRINTER TEST pdrstuvwxgz<!>+

8

SURETZ STANDARD:

CALIBRATION:

OPERATOR SIGNATURE

### FACE THIS SIDE DOWN - THIS EDGE IN FIRST

### **BAC DataMaster**

**Evidence Ticket** 

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204158 11/10/09

TESTING OFFICER: CARVER/DEWRYNE/D OFFICER I.D.: C41 PERMIT NUMBER: 920208 EXPIRATION DATE: 09/07/11 MISCELLANEOUS DATA: .04 VAPOR CALIBRATION CHECK GUTH LABS LOT 09010 EXP 1/6/2010

### --- SUPERVISOR MODE ---

BLANK TEST	. 999	13:04
INTERNAL STANDARD	VERIFIED	13:04
EXTERNAL STANDARD	.039	13:05
BLANK TEST	.000	13:05
EXTERNAL STANDARD	.040	13:06
BLANK TEST	.000	13:07
EXTERNAL STANDARD	.040	13:07
BLANK TEST	.000	13:08

M = 3SIM. = .1 AVG. = .0396

### FACE THIS SIDE DOWN - THIS EDGE IN FIRST

### **BAC DataMaster**

**Evidence Ticket** 

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204158 11/10/09

ARREST TIME: 00:00 SUBJECT NAME: Х DOB: 01/01/01 SEX: M STATE/D.L.: XX/X ARRESTING OFFICER: Х OFFICER I.D.: X TESTING OFFICER: CARVER/DEWAYNE/D OFFICER I.D.: C41 PERMIT NUMBER: 929208 EXPIRATION DATE: 09/07/11 MISCELLANEOUS DATA: RFI TEST

### --- BREATH AMALYSIS ---

BLANK TEST	.000	13:09
\INTERNAL STANDARD	VERIFIED	13:09
SUBJECT SAMPLE	.000	13:10
RADIO INTERFERENCE		

# State of Missouri DEPARTMENT OF HEALTH



## PERMIT TYPE II



### DEWAYNE D CARVER

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

cambrate, periorin neig repairs, a	nd operate the following breath analyzer(s):					
DATAMASTER						
for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986.						
09/07/09	Interim Director					
Number 920208	Director of State Public Health Laboratory  Mangart T. Brunelly					
Expires <u>09/07/2011</u>	Director, Department of Health					
MO 580-0771 (7-88)	Lab. 4 (R7-88)					